






(Example: with SB-27)










































5.1











Exposure Values


when using ISO100 film


Aperture setting (f) Shutter speed (sec)	1.0	1.4	2	2.8	4	5.6	8	11	16	22	32
8	-3	-2	-1	0	1	2	3	4	5	6	7
4	-2	-1	0	1	2	3	4	5	6	7	8
2	-1	0	1	2	3	4	5	6	7	8	9
1	0	1	2	3	4	5	6	7	8	9	10
1/2	1	2	3	4	5	6	7	8	9	10	11
1/4	2	3	4	5	6	7	8	9	10	11	12
1/8	3	4	5	6	7	8	9	10	11	12	13
1/15	4	5	6	7	8	9	10	11	12	13	14
1/30	5	6	7	8	9	10	11	12	13	14	15
1/60	6	7	8	9	10	11	12	13	14	15	16
1/125	7	8	9	10	11	12	13	14	15	16	17
1/250	8	9	10	11	12	13	14	15	16	17	18
1/500	9	10	11	12	13	14	15	16	17	18	19
1/1000	10	11	12	13	14	15	16	17	18	19	20
1/2000	11	12	13	14	15	16	17	18	19	20	21
1/4000	12	13	14	15	16	17	18	19	20	21	22





Maximum and minimum apertures differ depending on lens















Ai Lens



**Meter
Coupling
Guide**

Non-Ai type Lens














































































RTS

CONTAX

ML 50mm 1:1.4

YASHICA LENS

MADE IN JAPAN

CONTAX
REAL TIME WINDER







Flash Head

Normal
AUTO
Flash
Sensor

Hotshoe
Contact

TTL AUTO
Flash Contacts

Flash Ready
Light Signal
Contact

Shoe
Locking
Ring



22 • 16 • 11 • 8 • 56 • 4 • 28 • 2 • 14



A
2000
1000
500
250
125
60
30
15
8
4
2
1
2
LT
B



Exposure Computer Dial

Auto Flash
Range Guide

Flash
Mode
Selector

Flash-
Ready
Lamp/
Test
Button.

Auto
Check
Lamp

Extension Cord
Socket (With
Screw-on Cap)

Battery
Compartment
Cover

Power Switch
(ON/OFF)







